

## G2

型番	外径	刃幅	全長	内径	取付穴高さ	刃数
	$\phi D_c$	$l$	L	$\phi d$	$l$	Z
MCSE-G2-50X50X25.4	50	50	60	25.4	40	6
MCSE-G2-50X60X25.4	50	60	70	25.4	40	6
MCSE-G2-60X50X25.4	60	50	60	25.4	40	6
MCSE-G2-60X60X25.4	60	60	70	25.4	40	6
MCSE-G2-60X75X25.4	60	75	85	25.4	40	6
MCSE-G2-60X100X25.4	60	100	110	25.4	40	6
MCSE-G2-75X50X25.4	75	50	60	25.4	40	8
MCSE-G2-75X50X31.75	75	50	60	31.75	42	8
MCSE-G2-75X60X25.4	75	60	70	25.4	40	8
MCSE-G2-75X 60X31.75	75	60	70	31.75	42	8
MCSE-G2-75X 75X25.4	75	75	85	25.4	40	8
MCSE-G2-75X 75X31.75	75	75	85	31.75	42	8
MCSE-G2-75X100X25.4	75	100	110	25.4	40	8
MCSE-G2-75X100X31.75	75	100	110	31.75	42	8
MCSE-G2-90X60X25.4	90	60	70	25.4	40	10
MCSE-G2-90X60X31.75	90	60	70	31.75	42	10
MCSE-G2-90X75X25.4	90	75	85	25.4	40	10
MCSE-G2-90X75X31.75	90	75	85	31.75	42	10
MCSE-G2-90X100X25.4	90	100	110	25.4	40	10
MCSE-G2-90X100X31.75	90	100	110	31.75	42	10
MCSE-G2-100X60X25.4	100	60	70	25.4	40	10
MCSE-G2-100X60X31.75	100	60	70	31.75	42	10
MCSE-G2-100X75X25.4	100	75	85	25.4	40	10
MCSE-G2-100X75X31.75	100	75	85	31.75	42	10
MCSE-G2-100X100X25.4	100	100	110	25.4	40	10
MCSE-G2-100X100X31.75	100	100	110	31.75	42	10