

## G2

型番	外径	刃幅	内径	刃数
	$\phi D_c$	$l$	$\phi d$	Z
PC-G2-50X30X25.4	50	30	25.4	6
PC-G2-50X40X25.4	50	40	25.4	6
PC-G2-50X50X25.4	50	50	25.4	6
PC-G2-50X60X25.4	50	60	25.4	6
PC-G2-50X75X25.4	50	75	25.4	6
PC-G2-50X100X25.4	50	100	25.4	6
PC-G2-60X 30X25.4	60	30	25.4	6
PC-G2-60X 40X25.4	60	40	25.4	6
PC-G2-60X50X25.4	60	50	25.4	6
PC-G2-60X60X25.4	60	60	25.4	6
PC-G2-60X65X25.4	60	65	25.4	6
PC-G2-60X75X25.4	60	75	25.4	6
PC-G2-60X100X25.4	60	100	25.4	6
PC-G2-65X30X25.4	65	30	25.4	6
PC-G2-65X40X25.4	65	40	25.4	6
PC-G2-65X50X25.4	65	50	25.4	6
PC-G2-65X60X25.4	65	60	25.4	6
PC-G2-65X65X25.4	65	65	25.4	6
PC-G2-65X75X25.4	65	75	25.4	6
PC-G2-65X100X25.4	65	100	25.4	6
PC-G2-75X30X25.4	75	30	25.4	8
PC-G2-75X40X25.4	75	40	25.4	8
PC-G2-75X50X25.4	75	50	25.4	8
PC-G2-75X60X25.4	75	60	25.4	8
PC-G2-75X75X25.4	75	75	25.4	8
PC-G2-75X100X25.4	75	100	25.4	8
PC-G2-100X30X25.4	100	30	25.4	10
PC-G2-100X40X25.4	100	40	25.4	10
PC-G2-100X50X25.4	100	50	25.4	10
PC-G2-100X60X25.4	100	60	25.4	10
PC-G2-100X75X25.4	100	75	25.4	10
PC-G2-100X100X25.4	100	100	25.4	10
PC-G2-125X50X25.4	125	50	25.4	12
PC-G2-125X60X25.4	125	60	25.4	12
PC-G2-125X75X25.4	125	75	25.4	12
PC-G2-125X100X25.4	125	100	25.4	12
PC-G2-125X125X25.4	125	125	25.4	12
PC-G2-75X30X31.75	75	30	31.75	8
PC-G2-75X40X31.75	75	40	31.75	8
PC-G2-75X50X31.75	75	50	31.75	8
PC-G2-75X60X31.75	75	60	31.75	8
PC-G2-75X75X31.75	75	75	31.75	8
PC-G2-75X100X31.75	75	100	31.75	8
PC-G2-100X30X31.75	100	30	31.75	10
PC-G2-100X40X31.75	100	40	31.75	10
PC-G2-100X50X31.75	100	50	31.75	10
PC-G2-100X60X31.75	100	60	31.75	10
PC-G2-100X75X31.75	100	75	31.75	10
PC-G2-100X100X31.75	100	100	31.75	10
PC-G2-125X60X31.75	125	60	31.75	12
PC-G2-125X75X31.75	125	75	31.75	12
PC-G2-125X100X31.75	125	100	31.75	12
PC-G2-125X125X31.75	125	125	31.75	12