

G2

型番	角度	外径	刃長	首径	首長	全長	シャンク径	シャンク長	刃数
	α	ϕDc	l	$\phi D1$	Neck Length	L	ϕDs	l_s	z
SACS-G2-25X30°	30°	25	4.	8	15.	69	16	50	6
SACS-G2-30X30°	30°	30	5.	8	15.	70	16	50	6
SACS-G2-35X30°	30°	35	6.	10	20.	86	20	60	6
SACS-G2-40X30°	30°	40	7.	11	20.	87	20	60	6
SACS-G2-45X30°	30°	45	7.	15	20.	87	20	60	6
SACS-G2-50X30°	30°	50	8.	18	25.	93	25	60	8
SACS-G2-55X30°	30°	55	9.	19	25.	93	25	59	8
SACS-G2-60X30°	30°	60	10.	21	25.	105	32	70	8
SACS-G2-20X40°	40°	20	4.	7	12.	66	12	50	6
SACS-G2-25X40°	40°	25	5.	10	15.	70	16	50	6
SACS-G2-30X40°	40°	30	6.	11	15.	71	16	50	6
SACS-G2-35X40°	40°	35	8.	11	20.	88	20	60	6
SACS-G2-40X40°	40°	40	10.	12	20.	90	20	60	6
SACS-G2-45X40°	40°	45	12.	12	20.	92	20	60	6
SACS-G2-50X40°	40°	50	13.	15	25.	103	25	65	8
SACS-G2-55X40°	40°	55	15.	15	25.	105	25	65	8
SACS-G2-60X40°	40°	60	16.	17	25.	110	32	69	8
SACS-G2-15X45°	45°	15	3.	6	15.	60	12	42	4
SACS-G2-20X45°	45°	20	4.	9	14.	60	12	42	4
SACS-G2-25X45°	45°	25	6.	10	15.	72	16	51	6
SACS-G2-30X45°	45°	30	7.5	12	14.5	72	16	50	6
SACS-G2-35X45°	45°	35	10.	12	15.	85	20	60	6
SACS-G2-40X45°	45°	40	12.5	12	18.5	93	20	62	6
SACS-G2-45X45°	45°	45	13.	16	19.	95	25	63	6
SACS-G2-50X45°	45°	50	14.5	17	19.5	95	25	61	8
SACS-G2-55X45°	45°	55	15.5	20	19.5	100	25	65	8
SACS-G2-60X45°	45°	60	17.	22	22.	110	32	71	8
SACS-G2-65X45°	45°	65	18.	25	25.	125	42	82	8
SACS-G2-70X45°	45°	70	18.	30	28.	128	42	82	10
SACS-G2-75X45°	45°	75	18.	34	32.	132	42	82	10
SACS-G2-80X45°	45°	80	20.5	34	35.5	140	42	84	10
SACS-G2-90X45°	45°	90	23.5	37	39.5	145	42	82	12
SACS-G2-100X45°	45°	100	25.	44	38.	150	42	87	12
SACS-G2-15X50°	50°	15	4.	5	15.	60	12	41	4
SACS-G2-20X50°	50°	20	5.	8	14.	60	12	41	4
SACS-G2-25X50°	50°	25	7.	10	15.	72	16	50	6
SACS-G2-30X50°	50°	30	8.	12	14.	72	16	50	6
SACS-G2-35X50°	50°	35	10.	14	15.	85	20	60	6
SACS-G2-40X50°	50°	40	13.	14	18.	93	20	62	6
SACS-G2-45X50°	50°	45	15.	15	18.	95	25	62	6
SACS-G2-50X50°	50°	50	16.	17	17.	95	25	62	8
SACS-G2-55X50°	50°	55	16.	20	19.	100	25	65	8
SACS-G2-60X50°	50°	60	18.	23	22.	109	32	69	8
SACS-G2-15X55°	55°	15	4.	6	15.	60	12	41	4
SACS-G2-20X55°	55°	20	5.	9	14.	60	12	41	4
SACS-G2-25X55°	55°	25	7.	10	15.	72	16	50	6
SACS-G2-30X55°	55°	30	8.	14	14.	72	16	50	6
SACS-G2-35X55°	55°	35	10.	16	15.	85	20	60	6
SACS-G2-40X55°	55°	40	13.	17	18.	93	20	62	6
SACS-G2-45X55°	55°	45	15.	19	18.	95	25	62	6
SACS-G2-50X55°	55°	50	16.	21	17.	95	25	62	8
SACS-G2-55X55°	55°	55	17.	24	19.	100	25	64	8
SACS-G2-60X55°	55°	60	18.	28	22.	109	32	69	8
SACS-G2-15X60°	60°	15	5.	6	13.	60	12	42	4
SACS-G2-20X60°	60°	20	7.	9	11.	60	12	42	4
SACS-G2-25X60°	60°	25	12.	10	17.	72	16	43	6
SACS-G2-30X60°	60°	30	12.	12	15.	72	16	45	6
SACS-G2-35X60°	60°	35	15.	12	15.	85	20	55	6
SACS-G2-40X60°	60°	40	20.	12	18.	93	20	55	6
SACS-G2-45X60°	60°	45	20.	18	18.	93	25	55	6
SACS-G2-50X60°	60°	50	20.	20	20.	95	25	55	8
SACS-G2-55X60°	60°	55	25.	20	20.	100	25	55	8
SACS-G2-60X60°	60°	60	30.	22	22.	109	32	57	8
SACS-G2-65X60°	60°	65	30.	25	25.	125	42	70	8
SACS-G2-70X60°	60°	70	30.	30	28.	128	42	70	10
SACS-G2-75X60°	60°	75	30.	34	32.	132	42	70	10
SACS-G2-80X60°	60°	80	35.	34	35.	140	42	70	10
SACS-G2-90X60°	60°	90	40.	37	38.	148	42	70	12
SACS-G2-100X60°	60°	100	40.	46	38.	148	42	70	12
SACS-G2-15X65°	65°	15	5.	6	13.	60	12	42	4
SACS-G2-20X65°	65°	20	7.	8	11.	60	12	42	4
SACS-G2-25X65°	65°	25	12.	10	15.	72	16	45	6
SACS-G2-30X65°	65°	30	12.	13	15.	72	16	45	6
SACS-G2-35X65°	65°	35	15.	15	15.	85	20	55	6
SACS-G2-40X65°	65°	40	20.	15	18.	93	20	55	6
SACS-G2-45X65°	65°	45	20.	20	18.	93	25	55	6
SACS-G2-50X65°	65°	50	20.	24	20.	95	25	55	8
SACS-G2-55X65°	65°	55	25.	24	20.	100	25	55	8
SACS-G2-60X65°	65°	60	30.	26	22.	109	32	57	8
SACS-G2-15X70°	70°	15	5.	6	13.	60	12	42	4
SACS-G2-20X70°	70°	20	7.	8	11.	60	12	42	4
SACS-G2-25X70°	70°	25	12.	10	15.	72	16	45	6
SACS-G2-30X70°	70°	30	12.	13	15.	72	16	45	6
SACS-G2-35X70°	70°	35	15.	15	15.	85	20	55	6
SACS-G2-40X70°	70°	40	20.	15	18.	93	20	55	6
SACS-G2-45X70°	70°	45	20.	20	18.	93	25	55	6
SACS-G2-50X70°	70°	50	20.	24	20.	95	25	55	8
SACS-G2-55X70°	70°	55	25.	24	20.	100	25	55	8
SACS-G2-60X70°	70°	60	30.	26	22.	109	32	57	8
SACS-G2-15X75°	75°	15	5.	7	13.	60	12	42	4
SACS-G2-20X75°	75°	20	7.	10	11.	60	12	42	4
SACS-G2-25X75°	75°	25	12.	12	15.	72	16	45	6
SACS-G2-30X75°	75°	30	12.	15	15.	72	16	45	6
SACS-G2-35X75°	75°	35	15.	16	15.	85	20	55	6
SACS-G2-40X75°	75°	40	20.	21	18.	93	20	55	6
SACS-G2-45X75°	75°	45	20.	24	18.	93	25	55	6
SACS-G2-50X75°	75°	50	20.	24	20.	95	25	55	8
SACS-G2-55X75°	75°	55	25.	24	20.	100	25	55	8
SACS-G2-60X75°	75°	60	30.	30	22.	109	32	57	8
SACS-G2-15X80°	80°	15	5.	8	13.	60	12	42	4
SACS-G2-20X80°	80°	20	7.	11	11.	60	12	42	4
SACS-G2-25X80°	80°	25	12.	14	15.	72	16	45	6
SACS-G2-30X80°	80°	30	12.	15	15.	72	16	45	6
SACS-G2-35X80°	80°	35	15.	19	15.	85	20	55	6
SACS-G2-40X80°	80°	40	20.	19	18.	93	20	55	6
SACS-G2-45X80°	80°	45	20.	24	18.	93	25	55	6
SACS-G2-50X80°	80°	50	20.	24	20.	95	25	55	8
SACS-G2-55X80°	80°	55	25.	24	20.	100	25	55	8
SACS-G2-60X80°	80°	60	30.	30	22.	109	32	57	8