

G2

型 番	角度	外径	刃幅	内径	刃数
	α	ϕD_c	l	ϕd	Z
WAC-G2-75X15X45° X25.4	45°	75	15	25.4	12
WAC-G2-100X20X45° X25.4	45°	100	20	25.4	14
WAC-G2-100X25X45° X25.4	45°	100	25	25.4	12
WAC-G2-125X30X45° X25.4	45°	125	30	25.4	16
WAC-G2-125X30X45° X31.75	45°	125	30	31.75	16
WAC-G2-75X20X60° X25.4	60°	75	20	25.4	10
WAC-G2-100X25X60° X25.4	60°	100	25	25.4	12
WAC-G2-125X30X60° X25.4	60°	125	30	25.4	14
WAC-G2-125X30X60° X31.75	60°	125	30	31.75	14
WAC-G2-75X20X90° X25.4	90°	75	20	25.4	10
WAC-G2-100X25X90° X25.4	90°	100	25	25.4	12
WAC-G2-125X30X90° X25.4	90°	125	30	25.4	14
WAC-G2-125X30X90° X31.75	90°	125	30	31.75	14

STi30

型 番	角度	外径	刃幅	内径	刃数
	α	ϕD_c	l	ϕd	Z
WAC-STi30-75X15X45° X25.4	45°	75	15	25.4	12
WAC-STi30-75X20X60° X25.4	60°	75	20	25.4	10
WAC-STi30-75X20X90° X25.4	90°	75	20	25.4	10